

Group:	AVi147 Series Alternators	Notes:
Form:	SP4012_AVi147_Series	Service parts listing. (AVi147 Series)
Date:	May 24, 2012 (Rev: 0)	
File:	Service parts list section	

Component View	Front housing	Rotor	Stator	Rear housing	Rectifier assembly	Regulator	Rear cover
							
Part number	1	2	3	4	5	6	7
AVi147S3003HD	6524-21	A020520081	A023520040	A012520047	6524-25	1861802	6524-37
AVi147S3004HD	6524-21	A020520081	A023520040	A012520047	6524-25	-	6524-37
AVi147S3005HD	6524-71	A020520081	A023520040	6524-15	6524-11	-	6524-37
AVi147S3006HD	6524-71	A020520081	A023520040	6524-15	6524-25	1861802	6524-37
AVi147S3007HD	6524-21	A020520081	A023520040	A012520047	6524-25	1861800	6524-37
AVi147S3008HD	6524-71	A020520081	A023520040	6524-15	6524-25	1861802	6524-37
AVi147S3009HD	6524-95	6524-83	A023520040	6525-82	6524-25	1861802	6524-37
AVi147S3010HD	6524-103	A020520081	A023520040	6524-104	6524-25	1861802	6524-37
AVi147S3011HD	6524-114	A020520081	A023520040	6524-112	6524-25	1861802	6524-37
AVi147S3012HD	6524-71	A020520081	A023520040	6524-15	6524-25	1861802	6524-37
AVi147S3013HD	6524-95	6524-83	A023520040	6525-82	6524-25	1861802	6524-37
AVi147S3014HD	6524-71	A020520081	A023520040	6524-15	6524-25	-	6524-37
AVi147S3015HD	6524-21	A020520081	A023520040	A012520047	6524-25	1861802	6524-37
AVi147S3016HD	6524-21	A020520081	A023520040	A012520047	6524-25	1861804	6524-37
AVi147S3017HD	6524-95	6524-83	A023520040	6525-82	6524-25	-	6524-37
AVi147S3018HD	6524-103	A020520081	A023520040	6524-104	6524-25	-	6524-37
AVi147S3019HD	6524-21	A020520081	A023520040	A012520047	6524-25	1861802	6524-37
AVi147S3020HD	6524-103	A020520081	A023520040	6524-104	6524-25	1861802	6524-37
AVi147S3021HD	6524-21	A020520081	A023520040	A012520047	6524-25	1861806	6524-37

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

Prestolite Electric Ltd
Unit 48, The Metropolitan Park
12-16 Bristol Road, Greenford,
Middlesex
UB6 8UP, United Kingdom

Tel: +44 (0) 20 8231 1000
Fax: +44 (0) 20 8575 9575
eu_info@prestolite.com

Group:	AVi147 Series Alternators	Notes:
Form:	SP4012_AVi147_Series	Service parts listing. (AVi147 Series)
Date:	May 24, 2012 (Rev: 0)	
File:	Service parts list section	


Component View	Bearing kit	Pulley / Retainer kit	Hardware kit	Slip ring	Notes
					
Part number	8	9	10	11	
AVi147S3003HD	6524-132	6524-133A	6524-134A	A062520057	No pulley included.
AVi147S3004HD	6524-132	6524-133A	6524-134B	A062520057	No regulator / pulley included.
AVi147S3005HD	6524-132	6524-133A	6524-134B	A062520057	No regulator / pulley included.
AVi147S3006HD	6524-132	6524-133A	6524-134A	A062520057	No pulley included.
AVi147S3007HD	6524-132A	6524-133E	6524-134C SS	A062520057	
AVi147S3008HD	6524-132	6524-133B	6524-134A	A062520057	8pk, 55mm Pulley fitted.
AVi147S3009HD	6524-132A	6524-133	6524-134A	A062520057	No pulley included.
AVi147S3010HD	6524-132	6524-133D	6524-134A	A062520057	No pulley included.
AVi147S3011HD	6524-132	6524-133F	6524-134A	A062520057	
AVi147S3012HD	6524-132	6524-133B	6524-134A	A062520057	
AVi147S3013HD	6524-132A	6524-133	6524-134A	A062520057	No pulley included.
AVi147S3014HD	6524-132	6524-133A	6524-134A	A062520057	No regulator / pulley included.
AVi147S3015HD	6524-132	6524-133A	6524-134A	A062520057	No pulley included.
AVi147S3016HD	6524-132	6524-133A	6524-134A	A062520057	
AVi147S3017HD	6524-132A	6524-133	6524-134B	A062520057	No regulator / pulley included.
AVi147S3018HD	6524-132	6524-133D	6524-134B	A062520057	No regulator / pulley included.
AVi147S3019HD	6524-132	6524-133B	6524-134A	A062520057	
AVi147S3020HD	6524-132	6524-133C	6524-134A	A062520057	
AVi147S3021HD	6524-132	6524-133A	6524-134A	A062520057	

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

Prestolite Electric Ltd
Unit 48, The Metropolitan Park
12-16 Bristol Road, Greenford,
Middlesex
UB6 8UP, United Kingdom

Tel: +44 (0) 20 8231 1000
Fax: +44 (0) 20 8575 9575
eu_info@prestolite.com

Group:	AVi147 Series Alternators	Notes:
Form:	SP4012_AVi147_Series	Service parts listing. (AVi147 Series)
Date:	May 24, 2012 (Rev: 0)	
File:	Service parts list section	



Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

Prestolite Electric Ltd
Unit 48, The Metropolitan Park
12-16 Bristol Road, Greenford,
Middlesex
UB6 8UP, United Kingdom

Tel: +44 (0) 20 8231 1000
Fax: +44 (0) 20 8575 9575
eu_info@prestolite.com